

Reservoir Structural Report



28/12/2011

All State City Council

Reservoir Name	Carbonation	External Structure	External Coatings	Internal Structure	Internal Coatings
High St No1	0	4	4	4	4
High St No2	0	4	4	4	2
Reservoir Hill No1	76	2	4	3	4
Reservoir Hill No2	36	3	4	4	4
Reservoir Hill No3	0	3	4	4	4

Priority 0 Item requires immediate attention.
Priority 1 Item is in poor condition or otherwise non functional.
Priority 2 Item is to receive precedence during maintenance
Priority 3 Item is functional but deteriorated/ not in operational order.
Priority 4 Item is in good condition.