



H	ł	İ	g	h	St	N	0	1

WAE archived-closed off:

High St No1					
Project Category -	select				
Date:	11/05/2013	Client Name:	All State City Council		
WS #:	0	Reservoir Name:	High St No1		
Job No:	024897	Project Number:	0		
Cleaning Due:	5/11/2014	Inspection Due:	5/11/2014	Register No:	38
Raised By:	dbsAdmin			Date:	4/28/2015
Map Standard:	WGS 84				
Co-ord 1:	S 030 27 114	E 152 53 236			
Co-ord 2:					
NOW Projects					
Maintenance Item:	Priority	: Status:			
NOW - Entry hatch and Pla	tform				
Comments:					
The entry hatch is not sealed arou	und the edges and the platform a	area is not sealed against c	ontamination.		
Action taken by nomina	ited staff member/cont	tractor:			
Accepted or modified a	nd approved for actior	n:	Date:	No	
Comments:					
Finance approved:			Date:	No	
Comments:					
Work order issued:			Date:	No	
Comments:					
Work Order completed	and accepted:		Date:	No	
Comments:					

Date:

No





High St No2

Project Category -	Miscella	neous CAPEX			
Date:	23/05/2011	Client Name:	All State City Council		
WS #:	0	Reservoir Name:	High St No2		
Job No:	024913	Project Number:	0		
Cleaning Due:	5/23/2013	Inspection Due:	5/23/2013	Register No:	21
Raised By:	jillasam49			Date:	5/26/2012
Map Standard:	WGS 84				
Co-ord 1:	S 034 27 467	E 150 25 793			
Co-ord 2:					
General Projects					
Maintenance Item:	<u>Priority:</u>	Status:			
Install a davit system.					
Comments:					
Action taken by nomina Accepted or modified an Comments:			Date:	No	
Finance approved:			Date:	No	
Comments:					
Work order issued:			Date:	No	
Comments:					
Work Order completed a	and accepted:		Date:	No	
WAE archived-closed of	ff:		Date:	No	





Reservoir Hill No1							
Project Category - Level 2 Inspection							
Date:	14/06/2011	Client Name:	All State City (Council			
WS #:	01	Reservoir Name:	Reservoir Hill	No1			
Job No:	024937	Project Number:	0				
Cleaning Due:	6/14/2015	Inspection Due:	6/14/2015		Register No:	37	
Raised By:	hanbgg				Date:	9/26/2013	
Map Standard:	WGS 84						
Co-ord 1:	S 027 68 586	E 152 24 597					
Co-ord 2:							
General Projects							
Maintenance Item:	<u>Priority:</u>	Status:					
Level 2 Inspection							
Comments:							
Action taken by nominate Review all defects previously report Scope repair works for immediate at	ted in level 1 inspections. and planned projects.			40/05/004	0 V		
Accepted or modified an	nd approved for action	:	Date:	10/25/201	3 Yes		
Comments:							
Level 2 inspection contractors enga	aged -Spiffing Engineering. Will	provide quote and scope of	works.				
Finance approved:			Date:		No		
Comments:							
Work order issued: Comments:			Date:		No		
Work Order completed a	and accepted:		Date:		No		
Comments:							
WAE archived-closed of	f:		Date:		No		





Reservoir Hill No2							
Project Category -	NOW						
Date:	17/06/2011	Client Name:	All State City	Council			
WS #:	0	Reservoir Name:	Reservoir Hill	No2			
Job No:	024944	Project Number:	0				
Cleaning Due:	6/17/2026	Inspection Due:	6/17/2013		Register No:	39	
Raised By:	jillasam49				Date:	5/6/2015	5
Map Standard:	WGS 84						
Co-ord 1:	S 28 05 585	E 152 49 368					
Co-ord 2:							
NOW Projects							
Maintenance Item:	<u>Priority:</u>	Status:					
NOW - Vermin entry and H	atch cover						
Comments:							
Possums have been entering this to be sealed off ASAP. The hatch cov						eeds to	
Action taken by nomina	ted staff member/contr	ractor:					
A temporary barrier of chicken wire The tank has been isolated and div			ssum entry .				
Accepted or modified ar	nd approved for action	:	Date:	7/22/2015	5 Ye	es	
Comments:							
Three contractors have been approximately Responses from 2 companies have 01 Sept 15 Tank was cleaned and	e been received by 30 July 15, be	ut \$ are more than in budget	<u>.</u>				
Finance approved:			Date:		N	0	
Comments:							
Hatch renovations have been post	poned until the 16/17 FY.						
Work order issued:			Date:		N	0	
Comments:							
Work Order completed a	and accepted:		Date:		N	0	
Comments:							
WAE archived-closed of	ff:		Date:		N	0	





Reservoir Hill No4					
Project Category -	NOW				
Date:	12/08/2014	Client Name:	All State City Council		
WS #:	0	Reservoir Name:	Reservoir Hill No4		
Job No:	026079	Project Number:	0		
Cleaning Due:	8/12/2022	Inspection Due:	8/12/2018	Register No:	11
Raised By:	dbsAdmin			Date:	8/25/2014
Map Standard:	WGS 84				
Co-ord 1:	S 028 14 032	E 153 31 648			
Co-ord 2:					
NOW Projects					
Maintenance Item:	<u>Priority:</u>	Status:			
NOW - Entry hatch					
Comments:					
The hatch cover is not sealed when	re the ladder stiles pass through.				
Action taken by nomina	ted staff member/conti	ractor:			

Date:

Comments:

Comments:

Accepted or modified and approved for action:

Work order issued: Date: No

Comments:

Work Order completed and accepted: Date: No

Comments:

WAE archived-closed off:

Date:

No

No





Reservoir	Hill	No4	

110301101111111111104					
Project Category -	Roof Re	newal			
Date:	12/08/2014	Client Name:	All State City Council		
WS #:	0	Reservoir Name:	Reservoir Hill No4		
Job No:	026079	Project Number:	0		
Cleaning Due:	8/12/2022	Inspection Due:	8/12/2018	Register No:	40
Raised By:	Dbsad			Date:	7/24/2021
Map Standard:	WGS 84				
Co-ord 1:	S 028 14 032	E 153 31 648			
Co-ord 2:					
General Projects					
Maintenance Item:	Priority:	Status:			
Roof Renewal					
Comments:					
Action taken by nomina Accepted or modified a			Date:	No	
Comments:					
Finance approved:			Date:	No	
Comments:					
Work order issued:			Date:	No	
Comments:					
Work Order completed a	and accepted:		Date:	No	
WAE archived-closed of	ff:		Date:	No	