

27/06/2023

All State City Council

Reservoir Name	Carbonation	External Structure	External Coatings	Internal Structure	Internal Coatings
High St No1	0	 4	 4	 4	 4
High St No2	0	 4	 4	 4	 2
Reservoir Hill No1	76	 2	 4	 3	 4
Reservoir Hill No2	36	 3	 4	 4	 4
Reservoir Hill No3	0	 3	 4	 4	 4
Reservoir Hill No4	0	 4	 4	 3	 4

Priority 0 Item requires immediate attention.

Priority 1 Item is in poor condition or otherwise non functional.

Priority 2 Item is to receive precedence during maintenance

Priority 3 Item is functional but deteriorated/ not in operational order.

Priority 4 Item is in good condition.