

By storing basic information about any renovations carried out, ASAM becomes a quick reference guide for future works and previously used suppliers.

Renovations may include:

- Hatch upgrades
- New ladder installs
- Roof renovations
- Coating replacements
- Crack injection repairs
- Safety installations
- Nozzle and screen installations
- Ventilation upgrades
- Or any other works!

Login to ASAM

1. Go to www.asam.com.au and select the login button to go to the login page

Enter your unique login details

ASAM Realtime Login							
	Username						
asam	Passphrase						
	ОК	Clear					
Passphrases are case sensitive.							
Warning: Login attempts will be recorded.							

This site is best viewed at 1024 x 768 resolution.

ASAM Data Management – Online and Accessible



2. On the start-up page, select the reservoir which has been renovated, click continue

asam	Client	Asset	Search	Attachments	Reports
	Client Name:	User	User Name: ascc48		
Please select a Client and Re	servoir, Tank, W	/ater Quality, /	Aqueduct or Pu	Imp from the combo	boxes
Client: All s	State City Coun	cil		🗧 🗧 Search fo	or Asset
Asset: • Re	eservoir 🔾 Ta	ank OWate	r Quality	Aqueduct OPum	p
	011101				<u> </u>
High	St No2 rvoir Hill No1				
Rese	rvoir Hill No2				
Job No: 💿 Cu	Irrent Active Jo	b No. 🕞 Hist	oric Job No.		
					Continue

3. There are two renovation tabs on the left-hand side – one for External, one for Internal. Select the one you wish to use.

350		Client	Asset	Search	Attachme	ents Repo	rts Config	Maintenance	Aqua
		ent Name: /	All State City	Council				User Name	ascc48
Reservoir Details High St No2	Reservoir Na Client	ame	High St M All State	No2 City Council					
	Inspection Date	•	23/05/20	11					
General Details	WS # Project Number	,	0						
Cleaning	Asset Number		0						
Safety Mixer C.P.	Job Number		024913						
Penetrations Valuation	Location		off High	Street					
Comments	Map Datum Sta	ndard	WGS 84						
External Inspection	Co-Ord 1		S 034 27	467 E 150 25 79	13				
Condition	Co-Ord 2								
Renovations	Environment Ty	ype	Urban						
	Cleaning an	nd Inspe	ction						
General	Next Clean Du	e	23/05/2013		Next	Inspection Due	23/05/2013		
Condition									
Renovations	Details								
Comments	Construction V	Wall <mark>Ste</mark>	el	Construc	tion Floor	Steel	Construction	Roof Aluminium	i
Attachments	Shape	On	Ground	Depth (M))	8.60			
Insert Image	Length (M)	0.0	D	Breadth (M)	0.00	Diameter (M)	31.00	
Contractors	Floor Area (sq	m) 754	.39	Capacity	(ML)	6.49			
Contractor Roles	Commissioned	16/	08/1986	Service L	ife (Years)	70	Years to Run	42	

ASAM Data Management - Online and Accessible



4. Once at a renovations page, you can view previous renovation details. This one shows an entry hatch upgrade by an unknown contractor.

856	3	Client	Asset	Search	Attachments	Reports	Config	Maintenance	Aqua
	RT	Client Na	ne: All State City	/ Council				User Name:	ascc48
Reservoir Details									
High St No2		Not	es				Supplier		
	Edit	Delete 201	0 The entry hatc	h has been ren	ovated by local cont	ractors	Unknown	🔎 View	
General Details						1			
General Cleaning Safety Mixer C.P. Penetrations Valuation Comments	Add Ne	<u>.</u>							
External Inspection									
General Condition Coatings Renovations Comments									
Internal Inspection									
General Condition Coatings Renovations Comments									
Attachments									
View Images Insert Image									

ADDING A NEW RENOVATION

5. Click on 'Add New'

350	9M) /7/	Client Client Name:	Asset All State City	Search Council	Attachments	Reports	Config	Maintenance User Name:	Aqual ascc48
Reservoir Details High St No2	Notes								
General Details General Cleaning Safety Mixer C.P. Penetrations Valuation Comments	Add New								
External Inspection General Condition Coatings Renovations Comments									
Internal Inspection General Condition Coatings Renovations Comments									
Attachments View Images Insert Image									

ASAM Data Management - Online and Accessible



6. Enter the renovation details – include a date and contractor. If the contractor is not on the list, just type it into the details. Click 'ADD' to finalise.

35	am	Client	Asset	Search	Attachments	Reports	Config	Maintenance	Aqua
	RI	Client Name:	All State City	Council				User Name:	ascc48
Reservoir Details High St No2	Notes	_		_	_	Sur	oplier	7	
General Details	04/02/20	14 - Installed NE	EXTEP FRP L	adder			qualift ÷ Jualift		
Cleaning Safety Mixer C.P. Penetrations Valuation Comments	Add	Cancel				Ba Ba Bit Br Br De	yer yter tuminous Produ itish Paints itish Paints x	ucts	
External Inspection General Condition Coatings Renovations Comments						De Diu Du He Im Int Jo	x met ilux mpels p ernational tun		
Internal Inspection General Condition Coatings Renovations Comments						La Mi N/ PG Sh	farge Engineer rotone A xtep SH ield Technolog	ing Coatings	
Attachments View Images Insert Image									

ASAM Data Management - Online and Accessible